Property Address: 15827 Old Stagecoach Rd

City, State, ZIP: Pine, CO 80477

Start Date & Time: 12/02/2019 1:30pm End Date & Time: 12/04/2019 2:00pm

Location: Bedroom

Radon Monitor: Sun Nuclear 1027 s/n: 206105034

Time Interval: 1 Hr. Cailbration Date: 05/2019

	*EPA Protocl Avg: 9.9			
	Overall Avg.=		9.82	
Average	_		9.49	_
	9.8	6.9	10.2	
	11.3	9.8	12.0	
	11.6	9.8	8.3	
	8.3	8.3	7.6	_
-	Second 12 Hours			
Average			10.61	_
	13.1	9.1	12.8	
	12.8	12.8	10.2	
	10.2	10.6	15.0	
•	5.1	9.5	6.1	_
Day 2	First 12 Hours			
Average			10.83	-
	9.1	8.3	8.3	
	12.8	8.3	11.0	
	15.3	11.6	10.2	
	12.0	12.8	10.2	_
Average	Second 12 Hours			
Avorago	8.7	9.5	10.2 7.98	_
	10.2	12.4	10.2	
	5.5	6.1	9.5	
	4.7	3.6	5.1	
Day 1	First 12 Hours			_
	_	ntervai:		C



LIBERTY Home Inspections, LLC

PO Box 728 Pine, CO 80470 Phone: 720-515-7688

Understanding Radon
RADON OCCURS NATURALLY Radon is an invisible, radioactive gas created from natural deposits of uranium and radium in the soil.
Radon is easily drawn into homes through cracks and gaps in the foundation and can reach concentrations that increase the potential
for developing lung cancer. Although there are rare cases where radon comes from building materials, the major source of radon in
Colorado homes comes from natural deposits of uranium and radium commonly found in Colorado's soil. It is rarely caused by

The United States Surgeon General, the American Lung Association, and the Environmental Protection Agency recommend that people avoid long-term Radon exposure at or above 4 pCi/L.

The average radon level in U.S. homes are 1.3 pCi/L. The average radon level in ambient air is 0.4 pCi/L.

Mitigation is highly recommended.

mankind like other environmental concerns.

For Information visit: www.colorado.gov/pacific/cdphe/categories/services-and-information/environment/radon



Information on EPA Protocol Avg visit: https://www.epa.gov/sites/production/files/2014-08/documents/homes_protocols.pdf

